

Report ID: 26,478,525 3 Version: 12 Dec 2024 Created:

Make:	Suzuki	Model:	Swift	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2022	Registration:	PFR887	Reg Expiry:	02 May 2025	Engine			1
WoF Expiry:		Odometer:	17,837 Kms	Good No:	26478525	Oil level	~		
VIN:	JSAAZCA3S00552386	Next Service:	-	Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.									
						Performance	ン ン		
Key:		-0	D D			Radiator / Hoses (visual)	~		
S = scratch	Se	20		10/2	X	Transmission	V		
D = dent				1 - L	BID				
R = rust				10	VHIK	Operation	~		
PT = paint defe	ect			$\square \cup$		Noise	~		
C = crack P = pin dent	LHC					Clutch			~
* = decals	dic					CV joints	~		
SC = stone chi	ps US			10		Wheel bearings	~		
W = significant scuffs						Brakes			1
						Performance	~		
Body Insp	pection Comments	Note: son	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
						Left front	6.	.0	mm
						Right front	6.	.0	mm
						Left rear	6.	.5	mm
Conditions During Body Inspection: Dry						Right rear	6.0 mm		
						Spare	N/A		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Fwd						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			1
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
						Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
	I					Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RL Window winder RR			
						Rear view mirrors	<b>v</b>		
							<b>v</b>		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		
Road Conditions During Test Drive: Dry     Central locking							~		
Engine Ti	ming Mechanism	Timing	Chain			Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	ог сант вен керіас	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Marlon Espena Date: 10 Dec 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....