

## **Basic Vehicle Condition Guide**

Report ID: 26,478,998


Version: 4

Created: 08 Jan 2025

Make: Model: Skoda Fabia **Body Style:** Hatchback Year: 2019 Registration: MMZ295 Reg Expiry: 28 Nov 2024 WoF Expiry: **Odometer: Good No:** 79,542 Kms 26478998 VIN: TMBFC6NJ5LZ007306 **Next Service:** 80000 Service History:

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Failed WOF

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

## **General Comments**

-Brand New Battery!

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No

Kms:

_			
	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	<i>V V V</i>		
Performance	~		
Noise	~		
Cooling System	•	•	
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission	•		
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	4.0		mm
Right front	4.0		mm
Left rear	3.0		mm
Right rear	3.0		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories		ı	
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	V V V V V V		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	<b>V</b>		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	1	•	
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera	~		

Signature: .....

Inspected by: Sione Mae Date: 12 Dec 2024

Name: .....