

Report ID: 26,479,362 3 Version: 12 Dec 2024 Created:

Make:	Subaru	Model:	Impreza	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2009	<b>Registration:</b>	FDC164	<b>Reg Expiry:</b>	12 Dec 2024	Engine			
WoF Expiry:	23 Jan 2025	Odometer:	169,049 Kms	Good No:	26479362	Oil level	~		
VIN:	JF1GH7KF39G034414	Next Service:	179,000kms	Service Histor	y: No	Smoke & fumes	~		
	_					Performance	~		
	port is not a warranty a quide only. Consid		for age and mileage	e. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
	DS		SP P	S	SP	Performance	~		
Key:				500-		Radiator / Hoses (visual)	V		
S = scratch D = dent						Transmission			
B = rust	S SC	1		710	SDW	Operation	~		
PT = paint defect						Noise	V		
C = crack						Clutch	~		
P = pin dent	SC di			$\langle \rangle$	24114	CV joints	~		
* = decais						Wheel bearings	V		
SC = stone chips						Brakes			
W = significant scuffs P S S P						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
Body inspection comments						Tyres (lowest observed tread	d depth	of tyre	2s)
Paint flaking on left side sill.						Left front	5	.0	mm
						Right front	5.	.0	mm
						Left rear	4	.0	mm
Conditions During Body Inspection: Dry						Right rear	4	.6	mm
						Spare	Spare Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories	1		1
Seats	Good					Head lights	~		
						Tail lights	V		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
						Wipers (front & rear)	~		1
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
Cam belt has been replaced, but writing has worn off sticker. Left side dashboard air vent is faulty						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		•
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Repla	cement: N	No	Kms:		Reversing camera	~		
		Dete: 12 Dec 2024							
Inspected by: Jason Young Date: 12 Dec 2024									
I have read and understood this condition guide. Name:									