

Report ID: 26,479,391 Version: 1 11 Dec 2024 Created:

Make:	Mercedes-Benz	Model:	CLC	Body Style:	Hatchback	1		Pass	Fail	N/A	
Year:	2008	Registration:	GDR642	Reg Expiry:	01 Jan 2025	E	ngine			1	
WoF Expiry:	26 Jun 2025	Odometer:	112,586 Kms	Good No:	26479391		Oil level	~			
VIN:	WDB2037562E039983	Next Service:	overdue	Service Histor	y: No		Smoke & fumes	~			
						iŀ	Performance	~			
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or		Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System					
a full mechan	lical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	୲⊢	Coolant condition	~			
	S SC W		SW		S SC	11	Performance	~			
Key:	330	-0			330		Radiator / Hoses (visual)	~			
S = scratch D = dent						Т	Transmission			1	
R = rust	s sc			710	HIVSW		Operation	~			
PT = paint defe	ect NP	r I		$\left(\left \left(\right) \right\rangle \right)$			Noise	~			
C = crack					SC		Clutch			~	
P = pin dent	LENG HID				74116		CV joints	~			
* = decals	SDSC 91			-July	PT SC W		Wheel bearings	~			
SC = stone chips							Brakes				
W = significant scuffs S SC W W S D W S D							Performance	~			
Podylog	action Commonts	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	╟╴	Hand Brake	~			
body inspection comments						Tyres (lowest observed tread depth of tyres)				es)	
Windscreen stone chips										mm	
						╟╴	Right front	6		mm	
							Left rear			mm	
Conditions During Body Inspection: Dry						۰H	Right rear 6			mm	
Conditions During Body Inspection: Dry							Spare N/A				
Under Carriage & Under Bonnet Inspection Comments							Suspension				
No hoist ins	spection					⊢⊢	Suspension performance	~			
(Hoist brok	,						Steering performance	~			
Engine oil le	eak					╟╴	Shock absorbers	~			
						A	ir Conditioning / Heater	-			
						┙┝╴	Operation		~		
Interior Comments						E	· lectrical / Accessories				
Seats	Good					╟╴	Head lights	~			
	Average					╟╴	Tail lights	~			
Carpets	Average					⊢⊢	Indicators	~			
Panels	Average						Dashboard warning lights	~			
	Card						Wipers (front & rear)	~			
Dashboa	rd Good					⊢⊢	Window winder FL	~			
	1					ᆣ	Window winder FR	~			
General C	<u>Comments</u>						Window winder RL			~	
							Window winder RR			~	
							Rear view mirrors	~			
							Radio (basic test only)	~			
							CD (basic test only)	~			
							Number of keys	1		I	
Road Con	ditions During Test	Drive				. ⊢	Central locking				
			Dry			⊢⊢	Remote locking	~			
Engine Tir	ming Mechanism:	Timing (Chain				Sat. Nav. (basic test only)	-		~	
Evidence of Cam Belt Replacement: Not Applicable Kms:							Reversing camera			~	
	-									-	
Inspected	d by: Rowan Fey						Date: 11 Dec 202	24			

I have read and understood this condition guide.

Name:

Signature: