

Report ID: 26,479,971 2 Version: 12 Dec 2024 Created:

Make:	Mahindra	Model:	XUV	Body Style:	SUV		Pass	Fail	N/A
Year:	2022	Registration:	PDF108	Reg Expiry:	27 Jul 2025	Engine	1	1	L
WoF Expiry:	29 Jul 2025	Odometer:	41,340 Kms	Good No:	26479971	Oil level	~		
VIN:	MA1YV2LDVM6D77961	Next Service:	46,000 kms	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	V		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:		-0	SD SD	-161-	S	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust PT = paint defect C = crack P = pin dent						Operation	~		
						Noise	~		
						Clutch			~
						CV joints	~		•
*=decals S 919						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance			
Note: come defects % blomiches may not be displayed in the diagram						Hand Brake	~	V	
Body Inspection Comments								ofture	
						Tyres (lowest observed tread depth of tyres)			
									mm
						Right front			mm
						Left rear			mm
Conditions During Body Inspection: Dry						Right rear	3.5 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare			
onder carriage & onder bonnet inspection comments						Suspension			
Fwd						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
						Electrical / Accessories	1		
Seats	Average					Head lights	~		
Carpets	Poor					Tail lights	~		
						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
Dashbod	Good					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
Stone chip replace or fix, passenger seat cover torn, L fog light broken and not secure, front brake rotor and						Window winder RR	~		
pad low, re	ar brake rotor low,r rear	tyre punctured.				Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Marlon Espena						Date: 11 Dec 2024			
Inspected by: Marlon Espena Date: 11 Dec 2024									
I have read and understood this condition guide. Name:									