

Basic Vehicle Condition Guide

Report ID: 26,480,122


Version: 2

Created: 09 Jan 2025

Make: Model: Nissan **Pathfinder Body Style:** SUV Year: 2015 Registration: JLC953 Reg Expiry: 29 Dec 2024 **Odometer:** WoF Expiry: **Good No:** 23 Jan 2026 159,180 Kms 26480122 VIN: 5N1AR2MN7EC717377 Next Service: 174000km Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Surface corrosion in boot. Stone chips in windscreen.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

All ok

<u>Interior Comments</u>		
Seats	Good	
Carpets	Average	
Panels	Good	
Dashboard	Good	

Vehicle drove well.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Jayden Roxburgh Date: 09 Jan 2025

Name:

Pass	Fail	N/A
~		
~		
~		
~		
~		
~		
~		
•	•	
~		
~		
		~
~		
~		
~		
~		
d depth	of tyre	es)
6		mm
Yes		
~		
~		
~		
		1
~		
		1
~		
~		
~		
~		
~		
~		
	1	1
~		
~		
V		
\(\times \)		
\(\times \) \(\t		
V V V		
\(\frac{1}{V} \) \(\frac{1}{		
\(\frac{1}{V} \) \(\frac{1}{		
	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ

Signature: