

Report ID: 26,481,338 3 Version: 12 Dec 2024 Created:

Make:	Toyota	Model:	Hilux	Body Style:	Utility	] [	Pass	Fail	N/A	
Year:	2008	Registration:		Reg Expiry:	20 Feb 2025	Engine		I	1	
WoF Expiry:		Odometer:	271,807 Kms	Good No:	26481338	Oil level	~			
VIN:	MR0FZ22G701160118			Service Histor		Smoke & fumes	~			
					-	Performance	~			
	port is not a warranty	anation is maada	for one and miles as	Danta hava nat	haan diamontlad ar	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	harge.	Coolant condition	~			
						Performance	~			
Key:		-0	w w	-161-	W	Radiator / Hoses (visual)	~			
S = scratch							Transmission			
D = dent	scw 6/6			10	E SD	Operation	~			
R = rust PT = paint def				í In	JHH	Noise	~			
C = crack						Clutch	~			
P = pin dent					ᅰЦ	CV joints	~			
* = decals	sc 916			- AL	ELTP PTW	Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs PT W W W						Performance	~			
		Note: som	ne defects & blemishes	may not be disc		Hand Brake	v v			
Body Insp	pection Comments	10000.3011				Tyres (lowest observed tread	-	oftyre		
					Left front 5.0 mm					
						Right front				
						Left rear		.0	mm	
								.0	mm	
Conditions During Body Inspection: Dry						3			mm	
Under Carriage & Under Bonnet Inspection Comments						Spare No Suspension				
	indge a onder bor	ince inspectie	<u>on comments</u>			-				
						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater			1	
Interior Comments						Operation	~			
						Electrical / Accessories			1	
Seats	Poor					Head lights	~			
Carpets	Poor					Tail lights	~			
						Indicators	~		<u> </u>	
Panels	Poor					Dashboard warning lights	~		-	
Dashboa	rd Poor					Wipers (front & rear)	~			
						Window winder FL	~			
General	<u>Comments</u>					Window winder FR	~			
						Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)			~	
						Number of keys	1			
Road Conditions During Test Drive: Dry						Central locking		~		
Engine Timing Mechanicm: Comhelt						Remote locking		~		
Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: Yes Kms: 149,978						Sat. Nav. (basic test only)			~	
Evidence	oi Cam Beit Replac	ement: Y	′es	Kms: 14	19,978	Reversing camera			~	
Inspector	Inspected by: Greg Morgan Date: 11 Dec 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....