

Report ID: 26,481,580 2 Version: 12 Dec 2024 Created:

Make:	Toyota	Model:	Corolla	Body Style:	Wagon		Pass	Fail	N/A
Year:	2003	<b>Registration:</b>	BDF665	Reg Expiry:	05 Jul 2025	Engine	1		L
WoF Expiry:	18 Oct 2025	Odometer:	178,734 Kms	Good No:	26481580	Oil level	~		
VIN:	JTDER22E400112607	Next Service:	N/A	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		<u> </u>
						Performance	~		
	port is not a warranty		for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
	S		SD SD		Р	Performance	~		
Key:				500-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
R = rust	SPTW			20	S SC	Operation	~		
PT = paint defe	ect NP					Noise	~		
C = crack				TTX.	PT SC	Clutch			~
P = pin dent	PT				241 <u>16</u>	CV joints	~		
* = decals		10		10	E P	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
. significan	S W		DP		S	Performance	~		
Body Insp	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
Front left tyre worn on outer edges. Front right tyre wearing on edges						Left front	1.	6	mm
						Right front	2.	6	mm
						Left rear	5.	2	mm
Conditions During Body Inspection: Dry						Right rear	7.0 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Engine and transmission oil weep and seepage						Suspension performance	~		
-						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Wear on d	rivers side				Tail lights	~		
	wear on u					Indicators	~		
Panels	Good					Dashboard warning lights	~		<u> </u>
Dashboa	rd Good					Wipers (front & rear)	~		<u> </u>
	Good					Window winder FL	~		
Concert						Window winder FR	~		
General	<u>Comments</u>					Window winder RL	~		<u> </u>
						Window winder RR	~		ļ
						Rear view mirrors	~		<b> </b>
						Radio (basic test only)	~		
						CD (basic test only)	~		
L						Number of keys	2		<del></del>
Road Conditions During Test Drive: Dry						Central locking	~		<u> </u>
Enging Ti	ming Mechanism	Timina	Chain			Remote locking	~		<u> </u>
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	ог сапт вен керіас	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Hoani Saunders Date: 11 Dec 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....