

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends Cooling System

a full man chamical in an action which	to numbers and this can be among additional shares				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.		Coolant condition	~		
		Performance	~		
Key:	Radiator / Hoses (visual)	~			
S = scratch D = dent	Transmission				
R = rust PT = paint defect C = crack P = pin dent		Operation	~		
		Noise	~		
		Clutch			~
		CV joints	~		
*= decals		Wheel bearings	~		
SC = stone chips W = significant scuffs	Brakes				
		Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram		Hand Brake	~		
Fresh Cut & Polish!		Tyres (lowest observed tread depth of tyres)			s)
riesh Cut & Polish		Left front	5.0		mm
		Right front	5.0		mm
		Left rear	4.	0	mm
Conditions During Body Inspection: Dry		Right rear	5.0		mm
		Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments		Suspension			
		Suspension performance	~		
		Steering performance	~		
		Shock absorbers	~		
		Air Conditioning / Heater			
		Operation	~		
Interior Comments		Electrical / Accessories			
Seats Good		Head lights	~		
Carpets Good		Tail lights	~		
		Indicators	~		
Panels Good		Dashboard warning lights	~		
Dashboard Good		Wipers (front & rear)	~		
Dashboard Good		Window winder FL	~		
Concert Community		Window winder FR	~		
<u>General Comments</u>		Window winder RL	~		
		Window winder RR	~		
		Rear view mirrors	~		
		Radio (basic test only)	~		
		CD (basic test only)	~		
		Number of keys	2		
Road Conditions During Test Drive: Dry		Central locking	~		
		Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:		Sat. Nav. (basic test only)			~
Evidence of Cam Belt Repla	Reversing camera	~			
Inspected by: Sione Mae	Date: 12 Dec 2024				

I have read and understood this condition guide.

Name:

Signature:

Report ID: 26,481,624 3 Version:

Pass

V

V

V

V

Fail

N/A

06 Jan 2025 Created:

Engine

Oil level

Noise

Smoke & fumes

Performance