

Basic Vehicle Condition Guide

Report ID: 26,481,726


Version:

Created: 22 Dec 2024

Make: Model: Subaru ΧV **Body Style:** SUV Year: 2021 Registration: NTW34 Reg Expiry: 18 Oct 2025 WoF Expiry: **Odometer: Good No:** 03 Oct 2025 45,214 Kms 26481726 VIN: JF1GT7KL5MG124846 **Next Service:** 58500 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Under Carriage & Under Bonnet Inspection Comments

Conditions During Body Inspection:

Interior Comments				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

Wet

General Comments

Drives okay,

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Donovan Matara Date: 16 Dec 2024

Name:

	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes	~			
Performance	\(\times \)			
Noise	~			
Cooling System	•			
Coolant condition	~			
Performance	V			
Radiator / Hoses (visual)	~			
Transmission	•			
Operation	~			
Noise	~			
Clutch			~	
CV joints	~			
Wheel bearings	~			
Brakes	·	1	1	
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread	d depth	of tyre	es)	
Left front	5.6		mm	
Right front	5.6		mm	
Left rear	5.0		mm	
Right rear	5.0		mm	
Spare	Yes			
Suspension				
Suspension performance	~			
Steering performance	~			
Shock absorbers	~			
Air Conditioning / Heater			1	
Operation 🗸				
Electrical / Accessories			1	
Head lights	~			
Tail lights	~			
Indicators	~			
Dashboard warning lights	~			
Wipers (front & rear)	~			
Window winder FL	V V V V			
Window winder FR	~			
Window winder RL	~			
Window winder RR	~			
Rear view mirrors	~			
Radio (basic test only)	~			
CD (basic test only)	~			
Number of keys	2			
Central locking	<i>V</i>			
Remote locking	<i>y</i>			
Sat. Nav. (basic test only)			1	
Reversing camera	~			
neversing culliera				

Signature: