

Report ID: 26,481,892 2 Version: Created: 12 Dec 2024

Make:	Toyota	Model:	Hilux	Body Style:	Utility		Pass	Fail	N/A
Year:	1994	Registration:	ST4875	Reg Expiry:	08 Feb 2025	Engine	I	I	1
WoF Expiry:	21 Apr 2025	Odometer:	337,019 Kms	Good No:	26481892	Oil level	~		1
VIN:	7A433LNA609501599	Next Service:	?	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		-
	port is not a warranty	oration is made	for ago and miloago	Parts have not	been dismonthed or	Noise	~		-
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:	SSC S	-0	S D PT P S PT P		SDPW	Radiator / Hoses (visual)	~		+
S = scratch						Transmission			
D = dent	SDRSCW 616			The	EL DC	Operation	~		1
R = rust PT = paint def				\int	JHIH	Noise	~		
C = crack				+	S D PT P SC	Clutch	~		
P = pin dent						CV joints	~		
* = decals	SD PIE			AL.	SDP	Wheel bearings	~		
SC = stone chips						Brakes	V		
W = significant scuffs S SC W S S D PT P S PT P S S S D SC W						Performance	~		1
		Note: con				Hand Brake			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							/ /	oftur	
Dents & paint worn through on top edge of left & right side sills. Step plate grip pad is missing off middle of						Tyres (lowest observed tread depth of tyres)			
rear bumper.						Left front	-	.0	mm
						Right front	-	.0	mm
						Left rear	-	.0	mm
Conditions During Body Inspection: Dry						Right rear	9	.0	mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
onder carnage & onder Bonnet inspection comments						Suspension			·
Radiator/co	olant system needs nev	v antifreeze.				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	1		T
Interior Comments						Operation			~
						Electrical / Accessories			T
Seats	Average					Head lights	~		
Carpets	Good					Tail lights	~		<u> </u>
						Indicators	~		<u> </u>
Panels	Average					Dashboard warning lights	~		<u> </u>
Dashboa	rd Average					Wipers (front & rear)	~		<u> </u>
	rd Average					Window winder FL	~		<u> </u>
						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
-	in fabric on right side b			-		Window winder RR	~		
centre console. Switch blank missing out of right side of dashboard. Handle & lock missing off rear canopy door.						Rear view mirrors	~		
0001.						Radio (basic test only)		~	
						CD (basic test only)			~
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking			~
	-	_				Remote locking			~
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: Y	′es	Kms: 20	0,192	Reversing camera			~
							24		
Inspected by: Jason Young Date: 11 Dec 2024									
I have read and understood this condition guide. Name:									