

Report ID: 26,482,089 10 Version: 06 Jan 2025 Created:

Make:	Hyundai	Model:	H1	Body Style:	Van		Pass	Fail	N/A
Year:	2010	Registration:	FQR515	Reg Expiry:	10 May 2025	Engine	I		I
WoF Expiry:	17 Jan 2026	Odometer:	261,002 Kms	Good No:	26482089	Oil level	~		
VIN:	KMFWBX7JLBU283721	Next Service:	270000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	oration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional c	harge.	Coolant condition	~		
	S D R PT SC		SDRSC SD*		S D SC W	Performance	~		
Key:	130 MITSCILL	-0			303CW	Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust	s sc w			215	HIL DR	Operation	~		
PT = paint defe		IT I		$\left[\left(\right) \right]$		Noise	~		
C = crack						Clutch	~		
P = pin dent	LING HIS				74 <u>11</u> 4	CV joints			~
* = decals SRSC 919 *						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significant	S R SC		S D SC S D * SC		S D SC	Performance	~		
Body Incr	oction Commonts	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			
Rear door interior panel missing and door						Left front 5.0 m			mm
Right front							5.	.0	mm
						Left rear	4.	.0	mm
Conditions During Body Inspection: Dry						Right rear	4.0 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
engine oil weeps Runs on diesel fuel. Suspension performance						~			
Steering performance Shock absorbers							~		
							~		
Air Conditioning / Heat									
Operation							~		
Interior Comments						Electrical / Accessories			
Seats	marks, dri	vers hole				Head lights	~		
						Tail lights	~		
Carpets	Average					Indicators	~		
Panels	scratches	scuffs marks driv	ers broken			Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd scratches					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL			~
Air conditioning and, heating ok. speedo is slow to pick up speed reading on dial						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry Central locking							~		
Remote locking							~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
	d by: Gary Adams					Date: 13 Dec 20	24		
Inspected by: Gary Adams Date: 13 Dec 2024									

I have read and understood this condition guide.

Name:

Signature: