

Report ID: 26,482,805 Version: 1 Created: 19 Dec 2024

Make:	Nissan	Model:	Tiida	Body Style:	Hatchback		Pass	Fail	N/A	
Year:	2009	Registration:	JCS130	Reg Expiry:	06 May 2025	Engine			1	
WoF Expiry:		Odometer:	177,200 Kms	Good No:	26482805	Oil level	~			
VIN:	7AT0DH78X15350528	Next Service:	overdue	Service Histor	y: No	Smoke & fumes	~			
					-	Performance	~			
Note: This report is not a warranty This report is a guide only Consideration is made for age and mileage. Date have not been dismantled as						Noise		~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
						Coolant condition				
						Performance	~			
Key:	SC	-0	S S		S D	Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent	ISC 6/6			The	EID D	Operation	~			
R = rust				10	JHIH	Noise	~			
PT = paint def C = crack				+	SC	Clutch	•		~	
P = pin dent	Ho					CV joints	~			
* = decals	sc pip			AL.	ENP D	Wheel bearings	~			
SC = stone chips						Brakes	V			
W = significant scuffs SC S S W S D						Performance	~			
		Noto: con								
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake)	
Rear bumper damaged. Boot poor alignment.						Tyres (lowest observed tread depth of tyres)				
						Left front	3.0		mm	
						Right front		.0	mm	
r						Left rear		.0	mm	
Conditions During Body Inspection: Wet						Right rear	5.0 mm			
Under Comiene & Under Deservation Comments						Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
Air intake h	ose loose missing fixtur	res. No jack. Lhf t	yre bald on shoulders			Suspension performance		~		
						Steering performance		~		
						Shock absorbers	~			
						Air Conditioning / Heater				
Interior Commonte						Operation		~		
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
Carpets	Good					Tail lights	~			
	9000					Indicators	~			
Panels	Good					Dashboard warning lights	~			
Dachhar						Wipers (front & rear)	~			
Dashboa	rd Good					Window winder FL	~			
						Window winder FR	~			
General Comments					Window winder RL	~				
A/c and fan n/w. Infotainment unit n/w. Vehicle needs wheel alignment. Both front shock Top hats split.						Window winder RR	~			
Vibration w	hen idling					Rear view mirrors	~			
						Radio (basic test only)		~		
						CD (basic test only)		~		
						Number of keys	1			
Road Conditions During Test Drive: Wet Central locking							~			
						Remote locking	~			
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~	
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~	
г						L			1	
Inspecte	Inspected by: Reuben Harvey Date: 12 Dec 2024									

I have read and understood this condition guide.

Name:

Signature: