

Report ID: 26,482,908 1 Version: 08 Jan 2025 Created:

Make:	Polestar	Model:	Polestar 2	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2022	Registration:	PNG580	Reg Expiry:	19 Oct 2025	Engine			.I
WoF Expiry:	11 Oct 2025	Odometer:	68,309 Kms	Good No:	26482908	Oil level			~
VIN:	YSMVSEDA9PL11801:	Next Service:	0	Service Histor	y: No	Smoke & fumes			~
						Performance			~
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise			~
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	harge.	Coolant condition			~
						Performance			~
Key:		-0	S D	-01-		Radiator / Hoses (visual)			~
S = scratch						Transmission			
D = dent	SC DE			715	HILS	Operation	~		
R = rust PT = paint defe				$\left[\right] \left[\right]$		Noise	~		
C = crack				$+ \mathbf{\nabla}$		Clutch			~
P = pin dent	HIC				세비	CV joints	~		
* = decals	- Ole			The	ALL P	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs W D S W						Performance	~		
		Note: son	ne defects & blemishe	s may not be disp	layed in the diagram	Hand Brake	~		
Body Insp	pection Comments			, ,	, ,	Tyres (lowest observed tread	•	oftvre	l es)
						Left front 3 mr			
						Right front		3	mm
						Left rear		, 1	mm
Conditions Duving Rody Insportion.						Right rear		+ 1	 mm
Conditions During Body Inspection: Wet						Spare N/A			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
	-					Suspension performance	~		1
Front whee	l drive					Steering performance	~		
						Shock absorbers	~		-
						Air Conditioning / Heater	v		
						Operation	~		
Interior Comments						Electrical / Accessories			
						Head lights	~		T
Seals	Good								<u> </u>
Carpets	Average					Tail lights Indicators	v		
						Dashboard warning lights	~ ~		──
Panels	Average					Wipers (front & rear)	<i>v</i> <i>v</i>		──
Dashboa	rd Good					Window winder FL	<i>v</i> <i>v</i>		<u> </u>
						Window winder FL Window winder FR			──
General C	Comments					Window winder FR Window winder RL	V 		
						Window winder RL Window winder RR	~ ~		──
						Rear view mirrors			+
						Radio (basic test only)	v		
							~		-
						CD (basic test only)	1		~
		~ .				Number of keys	1		T
Road Conditions During Test Drive: Wet						Central locking	~		
Engine Tir	ning Mechanism:	Unknow	/n			Remote locking	~		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)	~		
				11113.		Reversing camera	~		
Inspected	d by: Xinghui Lin					Date: 08 Jan 202	25		
	· -								

I have read and understood this condition guide.

Name:

Signature: