

Report ID: 26,482,965 2 Version: 13 Dec 2024 Created:

Make:	Suzuki	Model:	Escudo	Body Style:	Wagon		Pass	Fail	N/A
Year:	2006	Registration:	MRY109	Reg Expiry:	18 Dec 2024	Engine			<u>I</u>
WoF Expiry:	27 Mar 2025	Odometer:	127,890 Kms	Good No:	26482965	Oil level	~		
VIN:	7AT0GK4MX1920044	Next Service:	131500	Service Histor	y: No	Smoke & fumes	~		
					-	Performance	~		
	port is not a warranty		C 1 11	D		Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
						Performance	~		
Key:	s sc	-0	P SC S SC		S SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	sc 6/6			The	S SC	Operation	~		
R = rust				10	JHIH	Noise	~		
PT = paint def C = crack				+	SC	Clutch	•		~
P = pin dent	Ho					CV joints	~		
* = decals	s sc gig				ELFR SSC	Wheel bearings	~		
SC = stone chips							Brakes		
W = significant scuffs SC SC SC W SC						Performance	~		T
		Note: com				Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							Ť	ofture	
Stone chips front window screen						Tyres (lowest observed tread depth of tyres) Left front 4.2			
Wheel cove	er all covered in scuffs, s	cratches					4.		mm
						Right front	5.		mm
						Left rear			mm
Conditions During Body Inspection: Dry						Right rear	5.3 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
onder earnage a onder bonnet inspection comments						Suspension			
No underbody inspection						Suspension performance	~		
4x4 unteste	edd					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
						Electrical / Accessories			
Seats	small hole	!				Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators	~		<u> </u>
Panels	Good					Dashboard warning lights	~		<u> </u>
Dashboa	rd waar or st	eering wheel are	d gaar knob			Wipers (front & rear)	~		<u> </u>
	wear on st	eering wheel and				Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry Central locking							~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
	d by: Melissa Wilson						24		
Inspected by: Melissa Wilson Date: 13 Dec 2024									

I have read and understood this condition guide.

Name:

Signature: