

Report ID: 26,483,066 Version: 1 Created: 12 Dec 2024

Make:	Volkswagen	Model:	Amarok	Body Style:	Utility		Pass	Fail	N/A
Year:	2013	Registration:	GUU380	Reg Expiry:	30 Jul 2025	Engine	1	L	L
WoF Expiry:	23 Sep 2025	Odometer:	211,332 Kms	Good No:	26483066	Oil level	~		
VIN:	WV1ZZZ2HZDA028896	Next Service:	215,800	Service Histor	V: No	Smoke & fumes	V		
						Performance	r		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	V		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
			PP			Performance	~		
Key:	P	-0			SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	SC DIE			ZIS		Operation	~		
R = rust PT = paint def				\prod		Noise	~		
C = crack				$+ \mathbb{N}$	PT SC	Clutch	~		
P = pin dent						CV joints			~
* = decals P SC P P						Wheel bearings	~		
SC = stone chips						Brakes	•		
W = significant scuffs SC S P P P S S S						Performance	~		
		Note: son	ne defects & blemishe	s may not be disp	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread	•	oftyre	
Lower front grill is cracked. Wing mirrors need painting.						Left front		,	mm
						Right front	8		mm
						Left rear			mm
							3		-
Conditions During Body Inspection: Dry						Right rear	-		mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	inage a onder boi	ince inspectio	<u>on comments</u>			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
						Electrical / Accessories	1		
Seats	Average					Head lights	~		!
Carpets	Average					Tail lights	~		<u> </u>
						Indicators	~		<u> </u>
Panels	Average					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
Dashboa	Good					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>					Window winder RL	~			
No keys for roof racks. Noise in pulley area. Reverse camera not working. Oil leaks.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
		_ ·				Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera		>	
Inspected by Lewis Dolamore						Data: 12 Dec 2024			
Inspected by: Lewis Dolamore Date: 12 Dec 2024									
I have read	and understood th	is condition c	uide. Name:			Signature:			