

Report ID: 26,484,185 Version: 1 12 Dec 2024 Created:

Make:	Toyota	Model:	Corona	Body Style:	Hatchback		Pass	Fail	N/A
Year:	1990	Registration:	TZ7576	Reg Expiry:	28 Feb 2025	Engine			
WoF Expiry:	19 Dec 2024	Odometer:	276,375 Kms	Good No:	26484185	Oil level	~		
VIN:	7A8H6050796065415	Next Service:	Unknown	Service Histor	y: No	Smoke & fumes	~		
Note: This report is not a warranty						Performance	~		
	a guide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and t	his can be arranged to	or an additional C	narge.	Coolant condition	~		
	S PT SC S		S PT SC S P SC	S	PT SC	Performance	~		
Key:		= (0)		505		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	s sc			10	SD SD	Operation	~		
PT = paint def	ect NP					Noise	~		
C = crack					PT	Clutch			~
P = pin dent	PT SC				24116	CV joints	~		
* = decals		10		10	SPT SPT	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = Significant scuris SDPT S SDPT SD SD SD PT						Performance	~		
Body Insr	pection Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			s)
Minor Windscreen chips.						Left front	4.4 mm		
						Right front	!	5	mm
						Left rear		1	mm
Conditions During Body Inspection: Dry						Right rear	:	3	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Oil weeps.						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation		~	
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Compate						Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Poor					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
Only hot air coming from Air Con. Drivers seatbelt frayed.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking			~
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Yes Kms: 224,844						Reversing camera			~
	d by: Chris McQuade					Date: 12 Dec 20	24		
Inspecte						Date: 12 Dec 20	24		

I have read and understood this condition guide.

Name:

Signature: