

Report ID: 26,484,673 1 Version: 19 Dec 2024 Created:

Make:	Suzuki	Model:	Baleno	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2017	Registration:	LAQ758	Reg Expiry:	15 Jan 2025	Engine			
WoF Expiry:	18 Dec 2025	Odometer:	111,214 Kms	Good No:	26484673	Oil level	~		
VIN:	MA3EWB52S00315927	Next Service:	121000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tr	his can be arranged to	or an additional c	narge.	Coolant condition	~		
	S W		PP		S	Performance	~		
Key:		=		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust				10	HI S	Operation	~		
PT = paint defe	ect NP					Noise	~		
C = crack					P SC	Clutch			~
P = pin dent	sc de				2416	CV joints	~		
						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W DPTP SP PT						Performance	~		
Body Inst	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
					Tyres (lowest observed tread depth of tyres)				
					Left front	4	.0	mm	
						Right front	3.	.8	mm
						Left rear	5.	.0	mm
Conditions During Body Inspection: Wet						Right rear	5.2 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Slight wea	r on front seats				Head lights	~		
Carpote	Card					Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd c 1					Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
Two key rer	notes, one isn't working	9				Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2	_	
Road Conditions During Test Drive: Wet						Central locking	~		
			cı ·			Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	~		
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Hoani Saunders Date: 12 Dec 2024									

I have read and understood this condition guide.

Name:

Signature: