

# **Basic Vehicle Condition Guide**

Report ID: 26,484,982

Version: 1


Created: 12 Dec 2024

Fail N/A

Make: Model: Volkswagen Touareg **Body Style:** SUV Year: 2004 Registration: CDL640 Reg Expiry: 24 Jan 2025 **Odometer:** Good No: WoF Expiry: 06 Mar 2025 212,953 Kms 26484982 VIN: WVGZZZ7LZ4D027226 Next Service: 0 Service History:

#### Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



## **Body Inspection Comments**

Note: some defects & blemishes may not be displayed in the diagram

LR tail light cracked, RF door mirror light broken,

Conditions During Body Inspection: Dry

#### **Under Carriage & Under Bonnet Inspection Comments**

Transmission and oil leak,

<u>Interior Comments</u>		
Seats	RF seat ripped torn,rear seat broken ,	
Carpets	wear,worn,stained ,	
Panels	some interior panels broken and worn,	
Dashboard	Poor	

### **General Comments**

Drives okay, engine check light is on, car shudders when idling, needs a service,

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Unknown

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Donovan Matara Date: 12 Dec 2024

~		
~		
~		
~		
•		
~		
~		
~		
•		
~		
~		
		~
~		
~		
,	•	
~		
~		
d depth	of tyre	es)
3	.7	mm
3.5		mm
6.4		mm
7.0 mm		mm
	Yes	
~		
~		
~		
	~	
~		
~		
~		
~		
~		
~		
~		
t		
~		
<b>v</b>		
-		
~	V	
~	V	
<i>V</i>	V	
1	V	
1	V	V
	3 3 6 7 V V V V	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ

I have read and understood this condition guide.

Name: .....

Signature: .....