

Report ID: 26,485,025 2 Version: 12 Dec 2024 Created:

Make:	Volkswagen	Model:	Jetta	Body Style:	Sedan		Pass	Fail	N/A	
Year:	2008	Registration:	JAG776	Reg Expiry:	20 Feb 2025	Engine	ı		•	
WoF Expiry:	28 Nov 2025	Odometer:	176,445 Kms	Good No:	26485025	Oil level	~			
VIN:	WVWZZZ1KZ8M196376	Next Service:	186500	Service Histor	y: No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty a quide only. Conside	eration is made	for age and mileage.	Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and tr	lis can be arranged to	r an additional C	narge.	Coolant condition	~			
	SCW					Performance	~			
Key: S = scratch		=(0)		5(0)-		Radiator / Hoses (visual)	~			
						Transmission				
R = rust	SW			10	SW	Operation	~			
PT = paint defe	ect NP					Noise	~			
C = crack				TTY .		Clutch			~	
P = pin dent	sc dl				74Hb	CV joints	~			
* = decals		10		10		Wheel bearings	~			
SC = stone chips W = significant scuffs						Brakes				
, significant	D W	C	D		D	Performance	~			
Body Inst	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~			
						Tyres (lowest observed tread depth of tyres)				
						Left front	6.	.0	mm	
						Right front	6.	6.0 m		
						Left rear	6.	.0	mm	
Conditions During Body Inspection: Wet						Right rear	6.0 mm		mm	
						Spare	N/A			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
WOF sheet	remarks, lower control	arm bushes and I	brakes will require wor	k soon		Suspension performance	~			
	·		·			Steering performance	~			
	Shock absorbers	~								
						Air Conditioning / Heater				
						Operation 🖌				
Interior Comments						Electrical / Accessories				
Seats	stained					Head lights	~			
Carpote						Tail lights	~			
Carpets	Average					Indicators	~			
Panels	door and I	nood trim loose				Dashboard warning lights	~			
Dashh	rd 6					Wipers (front & rear)	~			
Dashboa	rd Average					Window winder FL	~			
	-				 	Window winder FR	~			
General C	<u>Comments</u>					Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)			~	
						Number of keys	1			
Road Conditions During Test Drive: Dry							~			
						Remote locking	~			
-	Sat. Nav. (basic test only)			~						
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~	
Inspected	Inspected by: Greg Morgan Date: 12 Dec 2024									

I have read and understood this condition guide.

Name:

Signature: