

Report ID: 26,485,459 2 Version: 15 Dec 2024 Created:

Make:	Holden	Model:	Commodore	Body Style:	Sedan		Pass	Fail N/A	
Year:	2018	Registration:		Reg Expiry:	25 Mar 2025	Engine			
WoF Expiry:	20 Dec 2025	Odometer:	184,882 Kms	Good No:	26485459	Oil level	~		
VIN:	6G1FA5E51HL328882		-	Service Histor		Smoke & fumes	~		
			155000		, 110	Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
						Performance	~		
Key:	S SC	-0	S P SC S P SC		S SC	Radiator / Hoses (visual)	~		
S = scratch	Se	0			X	Transmission	V		
D = dent	sscw all				BID SSC	Operation	~		
R = rust				TIO	JHIN	Noise	~		
PT = paint def C = crack	ect M			+		Clutch			
P = pin dent	HC	KI						~	
* = decals	SSC PR				BIR SSC	CV joints Wheel bearings	<ul> <li>✓</li> <li>✓</li> </ul>		
SC = stone chips									
W = significant scuffs S SC S D P SC S D P SC S D P SC						Brakes			
		Notorer	ne defects & blemishe			Performance Hand Brake	~		
<u>Body Ins</u>	pection Comments	Note: son	le délècts à blemisne	s may not be disp	layed in the diagram			- ( to	
Hole in front bumper and misaligned /aftermarket nobs on roof further investigation needed/carpet in rear needs refitting						<b>Tyres</b> (lowest observed tread depth of tyres)			
						Left front	7	mm	
						Right front	7	mm	
					Left rear	4	mm		
Conditions During Body Inspection: Dry						Right rear	4 mm		
Under Carriage & Under Pennet Inspection Comments					Spare				
Under Carriage & Under Bonnet Inspection Comments						Suspension			
2wd/engine oil leak/						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	rear needs	refitting				Tail lights	~		
		rentang				Indicators	~		
Panels	scratch ma	arks				Dashboard warning lights	~		
Dashboa	rd balacterd	dach papal missi	22			Wipers (front & rear)	~		
	noies and	dash panel missi	iig			Window winder FL	~		
						Window winder FR	~		
<u>General (</u>	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)		~	
						Number of keys	4		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)		~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Jac 1	d by: Uriah Pepene					Date: 15 Dec 20	24		
Inspecte	u by: Onan repene					Date: 15 Dec 20	<b>۲</b>		

I have read and understood this condition guide.

Name: .....

Signature: .....