

Basic Vehicle Condition Guide

Report ID: 26,485,463

Pass

~

~

/

1

Version:

Engine

Oil level

Noise

Left rear

Right rear

Smoke & fumes

Performance

Cooling System

12 Dec 2024 Created:

Fail

N/A

1

mm

mm

mm

 mm


7

6

Make: Model: Mazda Mazda6 **Body Style:** Sedan Year: 2013 Registration: **HEH349 Reg Expiry:** 11 Dec 2024 WoF Expiry: **Odometer:** 12 Apr 2025 159,000 Kms **Good No:** 26485463 VIN: JM0GJ103100124180 **Next Service:** 166,878 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Front wheel drive, LH/F lower control arm rear bush split, Inside of LH/F mag has been welded, LH/F tyre is backwards on rim

<u>Interior Comments</u>						
Seats	Good					
Carpets	Good					
Panels	Good					
Dashboard	Good					

General Comments

Centre interior lights not working, Rear view mirror delaminating & loose on screen,

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Andre Richardson Inspected by:

Name:

\neg	Spare	Yes					
	Suspension						
	Suspension performance	~					
	Steering performance	~					
	Shock absorbers	~					
	Air Conditioning / Heater		•				
╡	Operation	~					
	Electrical / Accessories						
	Head lights	~					
	Tail lights	~					
	Indicators	V V					
	Dashboard warning lights	~					
	Wipers (front & rear)	V					
	Window winder FL	~					
=	Window winder FR	v					
	Window winder RL	· •					
	Window winder RR	~					
	Rear view mirrors	~					
	Radio (basic test only)	~					
	CD (basic test only)	~					
Ц	Number of keys	1					
	Central locking	~					
╡	Remote locking	~					
	Sat. Nav. (basic test only)	~					
	Reversing camera	'					
Date: 12 Dec 2024							
Signature:							

have rea	nd and	undarct	and thic	condition	auida