

Report ID: 26,486,502 3 Version: 18 Dec 2024 Created:

Make:	Toyota	Model:	Hiace	Body Style:	Van		Pass	Fail	N/A
Year:	2018	Registration:	LLA818	Reg Expiry:	07 Mar 2025	Engine			L
WoF Expiry:		Odometer:	362,841 Kms	Good No:	26486502	Oil level	~		
VIN:	JTFHT02PX00241723	Next Service:	-	Service Histor		Smoke & fumes	~		
	51111021 X00241725		570-1008111			Performance	~		┼──┤
Note: This report is not a warranty						Noise	~		+
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends									
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
Key:	S		S P SC S D PT		S P	Performance	~		<u> </u>
S = scratch						Radiator / Hoses (visual)	✓		
						Transmission			
R = rust						Operation	~		
PT = paint defect						Noise	~		
C = crack						Clutch			~
P = pin dent						CV joints	~		
* = decals SPT SPT						Wheel bearings	~		
W = significant scuffs						Brakes			
V – significant scurs S S S D S D S D S D S C						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
Passengers side front door close properly.						Left front 6 mm			
						Right front	6	5	mm
						Left rear	5	5	mm
Conditions During Body Inspection: Dry						Right rear		5	mm
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		T
Oil leak fror	n oil sump plug.					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	V		
						Operation			
Interior Comments						•	~		
						Electrical / Accessories			T
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		<u> </u>
						Indicators	~		<u> </u>
Panels	Average					Dashboard warning lights	~		<u> </u>
Dashboa	rd Good					Wipers (front & rear)	~		ļ!
						Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL			~
Vehicle drove ok.						Window winder RR			~
						Rear view mirrors	<		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Con	ditions During Tes	t Drive:	Dry			Central locking	~		
	-					Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: Y	′es	Kms: 14	9,702	Reversing camera			~
						-	-		
Inspected by: Aaron Johnson Date: 18 Dec 2024									
I have read and understood this condition guide. Name:									