

Report ID: 26,488,059 2 Version: 16 Dec 2024 Created:

| Make: | RAM | Model: | 1500 | Body Style: | Utility | | Pass | Fail | N/A |
|--|--------------------------|-----------------|------------------------|---------------------------------|----------------------|------------------------------|---------|---------|-----|
| Year: | 2019 | Registration: | MAS306 | Reg Expiry: | 03 Mar 2025 | Engine | I | | L |
| WoF Expiry: | 10 Sep 2025 | Odometer: | 169,234 Kms | Good No: | 26488059 | Oil level | ~ | | |
| VIN: | 1C6RR7FT5JS326722 | Next Service: | 172831 | Service Histor | y: No | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty | oration is made | for ago and milaago | Parts have not | been dismonthed or | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a full mechan | ical inspection prior to | purchase and th | nis can be arranged fo | r an additional o | harge. | Coolant condition | ~ | | |
| | | | S S | | Р | Performance | ~ | | |
| Key: | | -0 | | -01- | | Radiator / Hoses (visual) | ~ | | |
| S = scratch | | | | | | Transmission | | | |
| D = dent R = rust | | | | | | Operation | ~ | | |
| PT = paint defe | ect NP | | | $\left[\left(\right) \right]$ | | Noise | ~ | | |
| C = crack | | | | | | Clutch | | | ~ |
| P = pin dent | HE | | | | 74 <u>11</u> 4 | CV joints | ~ | | |
| *= decals | | | | | | Wheel bearings | ~ | | |
| SC = stone chips W = significant scuffs | | | | | | Brakes | | | |
| | | | | | Р | Performance | ~ | | |
| Body Insr | pection Comments | Note: som | ne defects & blemishes | may not be disp | layed in the diagram | Hand Brake | ~ | | |
| | | | | | | Tyres (lowest observed tread | d depth | of tyre | es) |
| Missing rear badges | | | | | | Left front | 4. | .0 | mm |
| | | | | | | Right front | 4. | .0 | mm |
| | | | | | | Left rear | 3. | .0 | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 3.0 mm | | |
| | | | | | | Spare Yes | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | < | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | | | |
| | | | | | | Operation 🖌 | | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Average | | | | | Head lights | ~ | | |
| Carpets | A | | | | | Tail lights | ~ | | |
| | Average | | | | | Indicators | ~ | | |
| Panels | Average | | | | | Dashboard warning lights | ~ | | |
| Dashboa | rd Average | | | | | Wipers (front & rear) | ~ | | |
| | rd Average | | | | | Window winder FL | ~ | | |
| | | | | | | Window winder FR | ~ | | |
| <u>General Comments</u> | | | | | | Window winder RL | ~ | | |
| Worn Steeri | ing Wheel | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 2 | | |
| Road Conditions During Test Drive: Dry | | | | | | Central locking | ~ | | |
| Engine Tir | ning Machanism | Timine | ^c hain | | | Remote locking | ~ | | |
| Engine Timing Mechanism: Timing Chain | | | | | | Sat. Nav. (basic test only) | | | ~ |
| Evidence of Cam Belt Replacement: Not Applicable Kms: Reversing camera | | | | | | | | | ~ |
| Inspected | d by: Sione Mae | | | | | Date: 14 Dec 20. | 24 | | |
| | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: