

Report ID: 26,488,063 Version: 1 20 Dec 2024 Created:

Make:	Hyundai	Model:	Veloster	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2012	Registration:	GLF629	Reg Expiry:	29 Jan 2025	Engine	1		
WoF Expiry:	23 Jul 2025	Odometer:	62,754 Kms	Good No:	26488063	Oil level	~		
VIN:	KMHTC61DVCU090154	Next Service:	71653	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Consid		for age and mileage	. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tr	lis can be arranged to	or an additional C	narge.	Coolant condition	~		
	S SC W		S SC		S SC	Performance	~		
Key: S = scratch		=(0)		5(0)-		Radiator / Hoses (visual)	~		
						Transmission			
B = cent R = rust SSC AB S						Operation	~		
PT = paint def	ect NP	1				Noise	~		
C = crack						Clutch			~
P = pin dent	PSC de				241 <u>14</u>	CV joints	<		
* = decals SC = stone chips						Wheel bearings	~		
W = significant scuffs						Brakes			
S SC W SC W SC						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
					Tyres (lowest observed tread depth of tyres)				
					Left front	6	;	mm	
						Right front	6 mr		mm
						Left rear	6.4 m		mm
Conditions During Body Inspection: Dry						Right rear	6.9 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
No underbody inspection						Suspension performance	~		
						Steering performance	~		
	Shock absorbers	~							
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
General	Comments					Window winder FR	~		
						Window winder RL	~		
						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Timing Mechanism: Timing Chain						Remote locking	~		
						Sat. Nav. (basic test only)			~
		.cment. N	lot Applicable	11115.		Reversing camera	~		
Inspected by: Melissa Wilson Date: 20 Dec 2024									

I have read and understood this condition guide.

Name: