

Report ID:	26,488,211					
Version:	1					

27 Dec 2024 Created:

Make:	Volkswagen	Model:	Beetle	Body Style:	Hatchback	1[Pass	Fail	N/A	
Year:	2008	Registration:	EHW848	Reg Expiry:	30 Apr 2025	[Engine				
WoF Expiry:	10 May 2025	Odometer:	78,005 Kms	Good No:	26488211		Oil level	~			
VIN:	WVWZZZ9CZ7M563551	Next Service:	87,000	Service Histor	y: Yes		Smoke & fumes	>			
						٦ľ	Performance	~			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or					IF	Noise	>				
diagnostic te	sting undertaken. The nical inspection prior to	vehicle has beer	n driven up to 50km/h	from cold. The	Vendor recommends	ιг	Cooling System		1		
a full mechar	lical inspection prior to	purchase and u	his can be arranged to	or an additional (.narge.	Jſ	Coolant condition	~			
	S		S		S	٦ľ	Performance	~			
Key: S = scratch		=		5(0)-			Radiator / Hoses (visual)	~			
D = dent	ATE				An	ŀ	Fransmission				
R = rust	s sc			10	HIL S	I.	Operation	~			
PT = paint def	ect NP	1				1	Noise	~			
C = crack					S SC	ΗF	Clutch			~	
P = pin dent	ssc de				2414	IF	CV joints	~			
* = decals		10		10]	Wheel bearings	~			
SC = stone chips					ļ	Brakes					
W = significant scuffs S S S						Performance	~				
Body Insi	pection Comments	Note: son	ne defects & blemishes	s may not be disp	layed in the diagram		Hand Brake	~			
				Ī	Tyres (lowest observed tread	l depth	of tyre	es)			
Headlights faded					Left front	2	.0	mm			
							Right front	3.	.0	mm	
						┚┠	Left rear	5	.0	mm	
Conditio	ns During Body Ins	pection:	Dry			٦٢	Right rear	5	.0	mm	
						╡ſ	Spare Yes				
Under Carriage & Under Bonnet Inspection Comments				Suspension							
							Suspension performance	>			
						П	Steering performance	~			
						Shock absorbers	~				
							Air Conditioning / Heater				
						ī[Operation	>			
Interior Comments					Electrical / Accessories						
Seats	marks						Head lights	~			
Carpots	A						Tail lights	~			
Carpets	Average						Indicators	>			
Panels	scratches	scuffs marks fabr	ic coming off				Dashboard warning lights	>			
Dashboa	ard						Wipers (front & rear)	~			
	ard scratches						Window winder FL	>			
	- -					īL	Window winder FR	~			
<u>General Comments</u>				Window winder RL			~				
Air conditioning and heating systems work at inspection.				Window winder RR			~				
							Rear view mirrors	~			
							Radio (basic test only)	~			
							CD (basic test only)	~			
						╧┟	Number of keys	2	1		
Road Con	ditions During Tes	t Drive:	Dry][Central locking	~			
Г. р. с. ¹		<u> </u>				ΪL	Remote locking	>			
Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: No Kms:				Sat. Nav. (basic test only)			~				
Evidence	or Cam Belt Replac	ement: N	lo	Kms:			Reversing camera			~	
Inspected by: Gary Adams Date: 17 Dec 2024											

I have read and understood this condition guide.

Name:

Signature: