

Report ID: 26,488,913 Version: 1 08 Jan 2025 Created:

Make:	Volkswagen	Model:	Golf	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2009	Registration:	KSN792	Reg Expiry:	17 Jan 2025	Engine			
	13 Jun 2025	Odometer:	121,503 Kms	Good No:	26488913	Oil level	~		
VIN:	WVWZZZ1KZAW040861	Next Service:	0	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	ical inspection prior to	o purchase and th	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
	SC S		SC	S	SC	Performance	~		
Key:				500-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
R = rust	S SC			20	S SC	Operation	~		
PT = paint def	ect NP	1				Noise	~		
C = crack				TTX.		Clutch			~
P = pin dent	HIS				74IIL	CV joints	~		
* = decals	- dl	10		10	BD SD	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
in significan	SC S	\mathcal{O}	S SC S P SC	S	S SC	Performance	~		
Body Insi	pection Comments	Note: som	ne defects & blemishe	s may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread	d depth	of tyre	:s)
						Left front	3.2	2	mm
						Right front	5.5	5	mm
						Left rear	7.	1	mm
Conditions During Body Inspection: Dry						Right rear	5.2 mm		mm
						Spare N/A			
<u>Under Ca</u>	rriage & Under Bo	nnet Inspectic	on Comments			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
						Electrical / Accessories			
Seats	minor sta	ins ,				Head lights	~		
Carpets	Average					Tail lights	~		
						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
						Window winder FL	~		
General (omments					Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
Drives okay	needs a service, shudd,	ers when idling,				Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	/		
						CD (basic test only) Number of keys			L
		(D)				Central locking	1		
Road Conditions During Test Drive: Dry						Remote locking	~ ~		
Engine Ti	ming Mechanism:	Cambeli	t						
-	of Cam Belt Replac		lo	Kms:		Sat. Nav. (basic test only) Reversing camera			~
Inspecte	d by: Donovan Mata	ra				Date: 16 Dec 20	24		

I have read and understood this condition guide.

Name:

Signature: