

Basic Vehicle Condition Guide

Report ID: 26,489,887


Version: 1

Created: 28 Dec 2024

Make: Model: Holden Commodore **Body Style:** Wagon Year: 2009 Registration: FMH135 Reg Expiry: 02 Jul 2025 WoF Expiry: **Odometer: Good No:** 02 Nov 2025 173,844 Kms 26489887 VIN: 6G1EK85759L315730 **Next Service:** 17/06/25 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



body inspection comments

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| Interior Comments | | | | | |
|-------------------|-------|---------|--|--|--|
| Seats | | Average | | | |
| Carpe | ets | Average | | | |
| Panel | s | Average | | | |
| Dashl | ooard | Average | | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Bryce Steele Date: 17 Dec 2024

Name:

| | Pass | Fail | N/A | | |
|--|----------------------------|------|----------|--|--|
| Engine | | | | | |
| Oil level | ~ | | | | |
| Smoke & fumes | v v | | | | |
| Performance | ~ | | | | |
| Noise | ~ | | | | |
| Cooling System | | | | | |
| Coolant condition | ~ | | | | |
| Performance | V | | | | |
| Radiator / Hoses (visual) | ~ | | | | |
| Transmission | | 1 | | | |
| Operation | ~ | | | | |
| Noise | ~ | | | | |
| Clutch | | | ~ | | |
| CV joints | ~ | | | | |
| Wheel bearings | ~ | | | | |
| Brakes | | Г | | | |
| Performance | ~ | | | | |
| Hand Brake | ~ | | | | |
| Tyres (lowest observed tread depth of tyres) | | | | | |
| Left front | 6. | .0 | mm | | |
| Right front | 6. | .0 | mm | | |
| Left rear | 5.0 | | mm | | |
| Right rear | 5. | .0 | mm | | |
| Spare | | Yes | | | |
| Suspension | | | | | |
| Suspension performance | <i>V V</i> | | | | |
| Steering performance | • | | | | |
| | | | | | |
| Air Conditioning / Heater | _ | | | | |
| Operation Electrical / Accessories | | | | | |
| | | | I | | |
| Head lights Tail lights | | | | | |
| Indicators | ./ | | | | |
| Dashboard warning lights | • | | | | |
| Wipers (front & rear) | ./ | | | | |
| Window winder FL | V V V V V V | | | | |
| Window winder FR | <i>y</i> | | | | |
| Window winder RL | <i>y</i> | | | | |
| Window winder RR | ~ | | | | |
| Rear view mirrors | ~ | | | | |
| Radio (basic test only) | ~ | | | | |
| CD (basic test only) | ~ | | | | |
| Number of keys | 2 | | | | |
| Central locking | · | | | | |
| Remote locking | ~ | | | | |
| Sat. Nav. (basic test only) | | | ~ | | |
| Reversing camera | | | · | | |
| <u> </u> | | | <u> </u> | | |

Signature: