

Report ID: 26,490,441 5 Version: 19 Dec 2024 Created:

Make:	Nissan	Model:	Leaf	Body Style:	Hatchback] [Pass	Fail	N/A	
Year:	2017	Registration:	PAM145	Reg Expiry:	26 Jul 2025	Engine	Engine				
WoF Expiry:	02 Jan 2026	Odometer:	183,819 Kms	Good No:	26490441	Oil level				~	
VIN:	7AT0DH8KX21224335	Next Service:		Service Histor	y: No	Smoke &	fumes	~			
						Performa	Performance				
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.							Noise				
							Cooling System				
a run mechan	lical inspection prior to	purchase and u	his can be arranged ic	or an additional of	.narge.	Coolant	condition	~			
						Performa	ance	~			
Key: S = scratch						Radiator	Radiator / Hoses (visual)				
						Transmiss	sion				
R = rust SC A A						Operatio	n	~			
PT = paint defe	ect NP					Noise		~			
C = crack						Clutch				~	
P = pin dent	sc				2416	CV joints	;	~			
*= decais						Wheel be	Wheel bearings				
SC = stone chips W = significant scuffs							Brakes				
						Performa	Performance				
Body Inst	pection Comments	Note: son	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Bra	ake	~			
						Tyres (lowest observed tread depth of tyres)				es)	
Left taillight cracked. Stone chip in windscreen.						Left from	Left front 2.5			mm	
						Right fro	Right front		3.0 m		
						Left rear		5.	.0	mm	
Conditions During Body Inspection: Dry						Right rea	Right rear 1.5 m			mm	
						Spare	Spare N/A				
Under Carriage & Under Bonnet Inspection Comments						Suspension					
						Suspensi	ion performance	~			
						Steering	performance	~			
						Shock ab		~			
						Air Conditioning / Heater					
Interior Commonts						Operation 🖌					
Interior Comments						Electrical / Accessories					
Seats	Good					Head lig	hts	~			
Carpets	Good					Tail light	S	~			
	Good					Indicator	ſS	~			
Panels	Good						rd warning lights	~			
Dashboa	ird Good					· · ·	front & rear)	~			
							winder FL	~			
Concert							winder FR	~			
<u>General Comments</u>						winder RL	~				
Battery SOH 73.95%. Tyre repair kit missing.							winder RR	~			
i yre repair	kit missing.					Rear view		~			
							asic test only)	~			
							c test only)			~	
						-	Number of keys 2				
Road Con	ditions During Tes	t Drive:	Dry			Central le	_	~			
Enging Ti	ming Mechanism	Unknow				Remote	-	~			
Engine Timing Mechanism: Unknown Evidence of Cam Belt Replacement: Not Applicable Kms:							(basic test only)			~	
Lvidence		ement. N	lot Applicable	11115.		Reversin	g camera	~			
Inspected	d by: Blair Robertson						Date: 16 Dec 20	24			
L	,										

I have read and understood this condition guide.

Name:

Signature: