

Report ID: 26,490,460 Version: 1 06 Jan 2025 Created:

Make:	BMW	Model:	3201	Body Style:	Wagon		Pass	Fail	N/A
Year:	2007	Registration:	MPT928	Reg Expiry:	22 May 2025	Engine			
WoF Expiry:	02 Jan 2026	Odometer:	117,980 Kms	Good No:	26490460	Oil level	~		
VIN:	WBAVW720X0A134550	Next Service:	127,000kms	Service Histor	y: No	Smoke & fumes		~	
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition 🖌			
				W		Performance	~		
Key:						Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust PT = paint defect C = crack						Operation	~		
						Noise	~		
						Clutch			~
P = pin dent SC d B						CV joints	~		
*= decais						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significant scutts W S						Performance 🖌			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
Windscreen moulding rubber part is gone.						Left front	3.5 mm		mm
Tyre sealer supplied in boot.						Right front	3	.5	mm
						Left rear	2	.5	mm
Conditions During Body Inspection: Wet						Right rear	2	.5	mm
						Spare N/A			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Oil weeping keeping with age and mileage.					Suspension performance	~			
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General Comments					Window winder RL	~			
Clips of Left rear trim for cargo blind lock is broken. (Can not fit correctly). Tail gate catch trim is missing. Right rear door actuator is not operating correctly (can not unlock by remote or central lock switch). Centre cup holder in dashboard is broken.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking		~	
						Remote locking		~	
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
							2.4		
Inspected by: Yuki Itohara Date: 20 Dec 2024									
I have read and understood this condition guide. Name:									