


<b>Make:</b> Hyundai	<b>Model:</b> I30	<b>Body Style:</b> Wagon
<b>Year:</b> 2010	<b>Registration:</b> FRP534	<b>Reg Expiry:</b> 22 Feb 2025
<b>WoF Expiry:</b> 15 Apr 2025	<b>Odometer:</b> 224,315 Kms	<b>Good No:</b> 26490769
<b>VIN:</b> KMHDB81DMBU101452	<b>Next Service:</b> 13-10-24	<b>Service History:</b> No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key:**

- S = scratch
- D = dent
- R = rust
- PT = paint defect
- C = crack
- P = pin dent
- \* = decals
- SC = stone chips
- W = significant scuffs



**Body Inspection Comments**

Note: some defects & blemishes may not be displayed in the diagram

Scratches, scuffs dings. Rusts on the top side of the rear inner right door.

**Conditions During Body Inspection:**

**Under Carriage & Under Bonnet Inspection Comments**

Oil due for service. Front right of the vehicle has a clicking noise when turning, further investigation is needed. Rear right window doesn't go up using the driver door switch, it does however go down using the driver switch and goes up with the rear right door switch.

**Interior Comments**

Seats	Average
Carpets	Average
Panels	Average
Dashboard	Average

**General Comments**

No comment.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Unknown  
Evidence of Cam Belt Replacement: Not Applicable Kms:

	Pass	Fail	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Performance	✓		
Noise	✓		
<b>Cooling System</b>			
Coolant condition	✓		
Performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand Brake	✓		
<b>Tyres</b> (lowest observed tread depth of tyres)			
Left front	5.0	mm	
Right front	5.0	mm	
Left rear	5.0	mm	
Right rear	5.0	mm	
Spare	Yes		
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	1		
Central locking	✓		
Remote locking			✓
Sat. Nav. (basic test only)			✓
Reversing camera			✓

Inspected by: My Auto Shop

Date: 24 Dec 2024

I have read and understood this condition guide. Name: ..... Signature: .....