

Report ID: 26,490,908 Version: 1 06 Jan 2025 Created:

Make:	lsuzu	Model:	D-MAX	Body Style:	Utility		Pass	Fail	N/A
Year:	2018	Registration:	LKS426	Reg Expiry:	25 Dec 2025	Engine			
WoF Expiry:	11 Jul 2025	Odometer:	185,224 Kms	Good No:	26490908	Oil level	~		
VIN:	MPATFS85JJT004674	Next Service:	195000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
	S R SC		S SC S PT W		S SC W	Performance	~		
Key:	13/130	-0		500-	3301	Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
B = rust	SPTW			710	SPW	Operation	~		
PT = paint defe	ect NP				70111	Noise	~		
C = crack					S	Clutch			~
P = pin dent	sscw dle				74116	CV joints	~		
* = decals		1		10	ED SW	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
vv = significant	S R P SC		S SC S W		S D W	Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			es)
						Left front 8			
						Right front	8	3	mm
						Left rear	5.	.5	mm
Conditions During Body Inspection: Dry						Right rear	5.	5.5 mm	
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	1		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Average					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
	-					Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	~		
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
	Inspected by: Beatrice Nelson Date: 06 Jan 2025								
Inspected by. Define reson Date: 00 Jair 2025									

I have read and understood this condition guide.

Name:

Signature: