

Report ID: 26,491,295 Version: 1 18 Dec 2024 Created:

Make:	Ssangyong	Model:	Actyon Sport	Body Style:	Utility		Pass	Fail	N/A
Year:	2015	Registration:		Reg Expiry:	08 Sep 2024	Engine		<u> </u>	
WoF Expiry:		Odometer:	182,978 Kms	Good No:	26491295	Oil level	~		
VIN:	KPADA1ETSEP197737	Next Service:	165,000 km	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		с I II	.		Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
						Performance	~		
Key:	P W	-0	SP SP		S D P	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	ssc 6/6			The		Operation	~		
R = rust				10	JHIH	Noise	~		
PT = paint defe C = crack				+		Clutch	•		
P = pin dent	Ho					CV joints	~		
* = decals	- Mik			- AL	EL SD	Wheel bearings	•		
SC = stone chips						Brakes	v		
W = significant scuffs S W SP SP DPTP						Performance	~		
		Note: son	ne defects & blemishes	may not be disr	laved in the diagram	Hand Brake	~		
Body Insp	pection Comments				ayea in the diagram		•	oftyre))
Bonnet guard damaged.						Tyres (lowest observed tread depth of tyres) Left front 3 mm			
R/R&L/R tail light cracked. L/R bumper reflector cracked.						Right front			
L/R bumper	r reflector cracked.					Left rear		5	mm
							6 mm		-
Conditions During Body Inspection: Dry						Right rear 6 mm			mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	indge a onder bor	meenspeede	<u>eoninento</u>			Suspension			
RWD.						Suspension performance	~		
L/R wheel hard to spin in air. Front tyres have outer edge wear.						Steering performance Shock absorbers	~		
							~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Seats	Poor					-	~		
Carpets	Good					Tail lights	~		
						Indicators	•		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
General (<u>Comments</u>					Window winder FR	~		
						Window winder RL	~		
	or glass cover broken. / gets stuck.					Window winder RR		~	
	gets staten.					Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	•		
						Number of keys	1		
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		
Engine Tir	ming Mechanism:	Timing (Remote locking	~		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
	or carri bert nepide			11113.		Reversing camera			~
Inspected	d by: Imraan Bryant					Date: 18 Dec 20	24		

I have read and understood this condition guide.

Name:

Signature: