

Basic Vehicle Condition Guide

Report ID: 26,491,380


Version: 2

Created: 09 Jan 2025

Make: Model: Hyundai Santa FE **Body Style:** SUV Year: 2016 Registration: JRP622 Reg Expiry: 25 May 2025 WoF Expiry: **Odometer:** 12 Nov 2025 237,228 Kms **Good No:** 26491380 VIN: KMHST81XSGU612765 **Next Service:** 244,000 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Vehicle has belly pans. Runs on Diesel fuel.

<u>Interior Comments</u>		
Seats	Average	
Carpets	Average	
Panels	Average	
Dashboard	Average	

General Comments

Air conditioning appears to be working fine and rather cold at inspection. Heater ok along with reverse camera

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Gary Adams Date: 19 Dec 2024

Pass	Fail	N/A
~		
~		
~		
~		
~		
~		
~		
~		
~		
		~
~		
~		
~		
~		
d depth	of tyre	es)
7	.0	mm
7.0		mm
Left rear 5.0		mm
5.0		mm
Yes		
~		
~		
~		
~		
~		
<i>v</i>		
~		
~		
\(\times \)		
\(\times \)		
~		
\(\times \)		
\(\times \) \(\t		
\(\times \) \(\t		
V V V V V V		
V V V V V		
V V V V V		
V V V V V V		
V V V V V V		
V V V V V V V V		
V V V V V V V V		
	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ

I have read and understood this condition guide.

Name:

Signature: