


<b>Make:</b> Mitsubishi	<b>Model:</b> Triton	<b>Body Style:</b> Utility
<b>Year:</b> 2019	<b>Registration:</b> MBC987	<b>Reg Expiry:</b> 26 Mar 2025
<b>WoF Expiry:</b> 27 Mar 2025	<b>Odometer:</b> 138,016 Kms	<b>Good No:</b> 26491749
<b>VIN:</b> MMAYLKK10KH011819	<b>Next Service:</b> 149,600 kms	<b>Service History:</b> No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key:**

- S = scratch
- D = dent
- R = rust
- PT = paint defect
- C = crack
- P = pin dent
- \* = decals
- SC = stone chips
- W = significant scuffs



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Rwd

Interior Comments

Seats	Average
Carpets	Average
Panels	Average
Dashboard	Good

General Comments

No canopy, driver seat torn and moving when driving, 3 air vent broken, gear shifter indicator broken, dash light on, missing rear view mirror, aerial missing, jack tools missing, gas switch broken, both front park light not working, L front shock leaking, turbo hose leaking.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain  
Evidence of Cam Belt Replacement: Not Applicable Kms:

	Pass	Fail	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Performance	✓		
Noise	✓		
<b>Cooling System</b>			
Coolant condition		✓	
Performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand Brake	✓		
<b>Tyres</b> (lowest observed tread depth of tyres)			
Left front	9	mm	
Right front	9	mm	
Left rear	9	mm	
Right rear	9	mm	
Spare		Yes	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights		✓	
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL			✓
Window winder RR			✓
Rear view mirrors		✓	
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. Nav. (basic test only)			✓
Reversing camera			✓

Inspected by: Marlon Espena

Date: 18 Dec 2024

I have read and understood this condition guide. Name: ..... Signature: .....