

Report ID: 26,493,952 2 Version: 18 Dec 2024 Created:

Make:	MG	Model:	ZS	Body Style:	SUV		Pass	Fail	N/A
Year:	2021	Registration:	NSL367	Reg Expiry:	06 Aug 2025	Engine			L
WoF Expiry:	11 Sep 2025	Odometer:	62,823 Kms	Good No:	26493952	Oil level			~
VIN:	LSJW74098MZ070213	Next Service:	78,000 kms	Service Histor	y: Yes	Smoke & fumes			~
						Performance			~
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise			~
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
			* *			Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust				210	HIV	Operation			~
PT = paint def	ect NP					Noise			~
C = crack					R	Clutch			~
P = pin dent	HIP				74116	CV joints	~		
* = decals	- Alt	10		10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
	W	e	* *		D	Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			
						Left front	4	4	mm
						Right front	3.	.5	mm
						Left rear	4	.5	mm
Conditions During Body Inspection: Dry						Right rear	5 mm		
						Spare N/A			
Under Ca	rriage & Under Bor	net Inspectio	on Comments			Suspension			
Fwd						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpote						Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd c i					Wipers (front & rear)	~		
	rd Good					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
Parcel tray	missing.					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1	1	
Road Conditions During Test Drive: Dry Central locking							~		
	ming Masheritan	T'				Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)	~		
Evidence	or Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspecte	d by: Marlon Espena					Date: 18 Dec 20	24		
						Dute			

I have read and understood this condition guide.

Name:

Signature: