

Report ID: 26,494,335 2 Version: 19 Dec 2024 Created:

Make:	Nissan	Model:	Vanette	Body Style:	Van		Pass	Fail	N/A
Year:	2004	Registration:		Reg Expiry:	11 Jun 2025	Engine			
WoF Expiry:	16 Oct 2025	Odometer:	191,312 Kms	Good No:	26494335	Oil level	~		
VIN:	7A8DH190807323554			Service History		Smoke & fumes	~		+
					· · · · ·	Performance	~		+
	port is not a warranty					Noise	~		+
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
						Performance	~		-
Key:	s sc	-0	S SC		S D SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	IS GIR				EID S	Operation	~		
R = rust					JHIH	Noise	~		-
PT = paint def C = crack				+	S SC	Clutch	~		+
P = pin dent	Htc					CV joints			~
* = decals	SDSC 91				S D SC	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC S SC S SC S SC S D R SC						Performance	~		T
		Noto: com			layed in the diagram		-		+
Body Inst	pection Comments	S NOLE: SOM	ie delects & Dieffils	nes may not be ulsp	ayeu in the uldyfall	Hand Brake	d dopth		
LH mirror missing. Rust in tailgate shut.						<b>Tyres</b> (lowest observed tread depth of tyres)			
Rear mirror missing. Chip in windscreen.						Left front		.0	mm
Rust above LF door. Dent in LH sill.						Right front	3.5		mm
						Left rear			mm
Conditions During Body Inspection: Dry						Right rear			
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	inage & onder boi	inet inspectic	<u>on comments</u>			Suspension		1	
Oil leaks.						Suspension performance	~		<u> </u>
Underbody	surface rust.					Steering performance	~		<u> </u>
						Shock absorbers	~		
						Air Conditioning / Heater		1	
Interior (	ommonte					Operation		~	
Interior Comments						Electrical / Accessories			
Seats	Poor, Rip	in both seats				Head lights	~		
Carpets	Card					Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Deskie						Wipers (front & rear)		~	
Dashboa	rd Average					Window winder FL		~	
						Window winder FR	~		
<u>General Comments</u>						Window winder RL			~
Radio not working.						Window winder RR			~
LF window fail.						Rear view mirrors		~	
Rear windo Heater fan 1	w washer fail. fail					Radio (basic test only)		~	
						CD (basic test only)			~
						Number of keys	1	1	
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking			~
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	cement: Y	'es	Kms: 14	1,250	Reversing camera			~
							1	1	
Inspecte	d by: Caleb Spicer Le	e				Date: 18 Dec 20	24		

I have read and understood this condition guide.

Name: .....

Signature: .....