

Report ID: 26,494,433 6 Version: 20 Dec 2024 Created:

Make:	BMW	Model:	3 Series	Body Style:	Sedan		Pass	Fail	N/A
Year:	2013	<b>Registration:</b>	QTB613	Reg Expiry:	27 Feb 2025	Engine	1		
WoF Expiry:	31 Dec 2025	Odometer:	130,852 Kms	Good No:	26494433	Oil level	~		
VIN:	WBA3D360X0NP71639	Next Service:	140,000kms	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged to	r an additional c	narge.	Coolant condition	~		
	l w			S		Performance	~		
Key:						Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust				210		Operation	~		
PT = paint defe	ect NP					Noise	~		
C = crack						Clutch			~
P = pin dent	sc				24114	CV joints	~		
* = decals		10		10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W – significan	PT W		P P		PT	Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			
						Left front	5.0 mm		
						Right front	5	.0	mm
						Left rear	5	.0	mm
Conditions During Body Inspection: Dry						Right rear	5.0 mm		mm
						Spare	N/A		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
]						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Correcto						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashhar						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
	-					Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	~		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	~		
Inspected by: Yuki Itohara Date: 18 Dec 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....