

Report ID: 26,494,524 1 Version: 17 Dec 2024 Created:

Make:	Honda	Model:	FIT	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2013	Registration:	LPR855	Reg Expiry:	17 Mar 2025	Engine	1	I	1
WoF Expiry:	22 Oct 2025	Odometer:	96,448 Kms	Good No:	26494524	Oil level	~		
VIN:	7AT08G2YX18021557	Next Service:	-	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	oration is made	for ago and milaago	Parts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:	L	-0	P SC S P	-161-	s	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	SC DIE			TIN	FIL S	Operation	~		
R = rust PT = paint def				$\left(\left \right\rangle \right)$		Noise	~		
C = crack				+		Clutch			~
P = pin dent	HIC				거네	CV joints	~		
* = decals	PSC 916			-Jul	ELD P	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S S P P SC S P S P						Performance	~		
Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed treat	-	oftyre	 es)
						Left front 6 mm			
						Right front		.2	mm
						Left rear		.2	mm
Conditions During Pody Inspection:						Right rear		.0 5	mm
Conditions During Body Inspection: Dry						Spare N/A			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
	-	·				Suspension performance	~		
Minor dent	in left and right sills.					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories	•		
Seats Average						Head lights	~		
	Avelage					Tail lights	~		
Carpets	Average					Indicators	~		
Panels	A					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
						Window winder FR	~		
General Comments					Window winder RL	~			
Radio screen needs Security Code. Mirror mounted camera works but not radio.						Window winder RR	~		
	in needs security code.	itoi mounteu	camera works but not			Rear view mirrors	~		
						Radio (basic test only)	+	~	
						CD (basic test only)		-	~
						Number of keys	2		•
Road Conditions During Test Drive: Dry						Central locking	2 V		
Road Conditions During Test Drive: Dry						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	-		~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	~		-
	•					-			
Inspecte	d by: Chris McQuade					Date: 17 Dec 20	24		

I have read and understood this condition guide.

Name:

Signature: