

Report ID: 26,494,744 2 Version: 23 Dec 2024 Created:

Make:	Mitsubishi	Model:	Pajero	Body Style:	Wagon		Pass	Fail	N/A
Year:	2014	<b>Registration:</b>	QYH278	Reg Expiry:	20 May 2025	Engine			
WoF Expiry:	18 Oct 2025	Odometer:	170,520 Kms	Good No:	26494744	Oil level	~		
VIN:	7AT0CJ08X24700410	Next Service:	180,000	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
diagnostic te	sting undertaken. The	vehicle has beer	n driven up to 50km/l	n from cold. The	Vendor recommends	Cooling System			1
a full mechar	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:		$-\infty$		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust	S SC			710	HIV	Operation	~		
PT = paint def	ect NP	r I		$\left( \left  \left( \right) \right\rangle \right)$	70H	Noise	~		
C = crack						Clutch			~
P = pin dent	ssc de				7414	CV joints	~		
* = decals				To .		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
vv = significan						Performance	~		
Body Inc	action Commonts	Note: som	ne defects & blemishe	s may not be disp	played in the diagram	Hand Brake	~		
Body Inspection Comments						<b>Tyres</b> (lowest observed tread depth of tyres)			
No Jack						Left front 8.0 mm			
						Right front	8.	0	mm
						Left rear	8.	0	mm
Conditions During Body Inspection: Dry						Right rear	8.0 mm		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			<u> </u>
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
						Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
	· ·					Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		-
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
Inspected by: Gary Adams Date: 18 Dec 2024									

I have read and understood this condition guide.

Name: .....