

Basic Vehicle Condition Guide

Report ID: 26,495,520


Version:

Created: 20 Dec 2024

Make: Model: Mitsubishi Triton **Body Style:** Utility Year: 2014 Registration: HMM387 Reg Expiry: 26 Sep 2025 WoF Expiry: **Odometer:** 17 Oct 2025 270,007 Kms **Good No:** 26495520 VIN: MMAJYKB40FD006554 **Next Service:** 275,000 kms **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

4wd

<u>Interior Comments</u>				
Seats	Poor			
Carpets	Poor			
Panels	Poor			
Dashboard	Average			

General Comments

Inspected by:

Noise when driving no power, front wiper blade torn, driver seat torn, both head light faded, air box plastic not secured, both side step bar dent and rust, rear step bar push in, front bumper grill broken, both rear shock leaking, R rear diff leak.service

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Yes Kms:

Date: 20 Dec 2024

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	~		
Noise		~	
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission	•		
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes		l .	-
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	5 mm		mm
Right front	5.5		mm
Left rear	4.5		mm
Right rear	4.5		mm
Spare	Yes		
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	-	~	
Air Conditioning / Heater			
Operation	V		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	, v		
Dashboard warning lights	~		
Wipers (front & rear)	-	~	
Window winder FL	~		
Window winder FR	<i>'</i>		
Window winder RL	~		
Window winder RR			
Rear view mirrors	~		
Radio (basic test only)	V		
CD (basic test only)	2		
Number of keys	2		1
Central locking	<i>'</i>		
Remote locking	~		_
Sat. Nav. (basic test only)			'
Reversing camera	I	1	V

I have read and understood this condition guide.

Marlon Espena

Name [,]			

183,385