

Report ID: 26,495,928 Version: 1 Created: 24 Dec 2024

Make:	Mazda	Model:	CX-9	Body Style:	SUV		Pass	Fail	N/A
Year:	2016	Registration:	KBW141	Reg Expiry:	13 Mar 2025	Engine	1	1	I
WoF Expiry:	06 Sep 2025	Odometer:	169,353 Kms	Good No:	26495928	Oil level	~		
VIN:	JM0TC2WLA0010258	Next Service:	179000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0		-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	SC 6			ZIS	HIL S	Operation	~		
R = rust PT = paint defect						Noise	~		
C = crack						Clutch			~
P = pin dent						CV joints	~		
* = decals SC 919						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC S SC S						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of		oftvre	25)
Minor stone chips on windscreen									mm
						Right front		.5	mm
						Left rear		.0	mm
Condition	as During Pody Inc	noction	Duri			Right rear		.0	 mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
Front whee	l drive					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation			
Interior Comments						Electrical / Accessories		•	
Seats Good						Head lights	~		
	Good					Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Card					Dashboard warning lights	~		
	Good					Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
Partial service history (last recorded in booklet at 100628kms)						Window winder RR	~		
A/C does not go cold						Rear view mirrors	~		-
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		I
Road Conditions During Test Drive: Dry						Central locking	2 V		
Road Conditions During Test Drive: Dry						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	~		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	~		
	-								
Inspecte	d by: Jaykib Collins					Date: 18 Dec 20	24		

I have read and understood this condition guide.

Name:

Signature: