

Report ID: 26,496,120 5 Version: 12 Jan 2025 Created:

Make:	Mazda	Model:	Axela	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2014	Registration:	QBZ719	Reg Expiry:	07 Mar 2025	Engine	1	<u> </u>	L
WoF Expiry:	12 Apr 2025	Odometer:	108,405 Kms	Good No:	26496120	Oil level	~		
VIN:	7AT0C13JX23107414	Next Service:	118000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		for and milago	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.									
a full mechan	ical inspection prior to	purchase and tl	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	SC	-0	S S	-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	SSC 61			10	EID S	Operation	~		
R = rust PT = paint defe				\prod	JHIH	Noise	~		
C = crack					D R SC	Clutch	•		~
P = pin dent	Ho					CV joints	~		•
* = decals	sc 916			- AL	EIIP I	Wheel bearings	~		
SC = stone chips						Brakes	•		
W = significant scuffs S SC W P SC						Performance	~		
		Note: son	e defects & blemishes	may not be disr	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							-	ofture))
Dents in roof						Tyres (lowest observed tread depth of tyres) Left front 5.0 mm			
									mm
						Right front Left rear		.0	mm
						ı ————	7		mm
Conditions During Body Inspection: Dry						Right rear 6.0 mm			mm
Under Carriage & Under Bonnet Inspection Comments						Spare N/A			
and charter bonnet inspection comments						Suspension			-
Battery pas	sed test					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		
	Avelage					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	Ird Average					Wipers (front & rear)	~		
	rd Average					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
A/c, reverse camera and nav good at time of inspection. Parcel tray missing.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	~		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	~		
·	LL Devilence LL		24		-				
Inspected by: Reuben Harvey Date: 27 Dec 2024									

I have read and understood this condition guide.

Name:

Signature: