

Basic Vehicle Condition Guide

Report ID: 26,496,274


Version: 1

Created: 04 Jan 2025

Make: Model: Honda Jazz **Body Style:** Hatchback Year: 2007 Registration: DSK893 Reg Expiry: 01 May 2025 WoF Expiry: **Odometer:** 07 Mar 2025 252,325 Kms **Good No:** 26496274 VIN: JHMGD38407S20030 **Next Service:** 230,000 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Water in spare wheel tub. Lhs sill trim missing and sill dented. Headlights faded. Rh fog light missing. Rear bumper damaged. Stone chips with crack in cva

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Shudder in trans. Oil approximately 1/2. Runs on 91 octane fuel

| <u>Interior Comments</u> | | | |
|--------------------------|------------------------|--|--|
| Seats | marks | | |
| Carpets | hole driver footwell | | |
| Panels | scratches scuffs marks | | |
| Dashboard | scratches | | |

General Comments

Cvt transmission shudders when taking off from standing position. Air conditioning feels average, heater ok. Remote nw. Both front seatbelt doesn't retract fully

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Gary Adams Date: 20 Dec 2024

Name:

| Create | a: o- | + Jan 2 | 023 |
|------------------------------|--|---------|----------|
| | Pass | Fail | N/A |
| Engine | | | |
| Oil level | | ~ | |
| Smoke & fumes | ~ | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | | | |
| Coolant condition | ~ | | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | | |
| Operation | | ~ | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | l depth | of tyre | ⊥ ≥s) |
| Left front | | .0 | mm |
| Right front | 7.0 | | mm |
| Left rear | 7.0 | | mm |
| Right rear | 5.0 | | mm |
| Spare | Yes | | |
| Suspension | | | |
| Suspension performance | V | | |
| Steering performance | <i>y</i> | | |
| Shock absorbers | · · | | |
| Air Conditioning / Heater | _ | | |
| Operation | ~ | | |
| Electrical / Accessories | | | |
| Head lights | ., | | |
| Tail lights | ~ | | |
| Indicators | | | |
| Dashboard warning lights | V | | |
| Wipers (front & rear) | | | |
| Window winder FL | ν ν | | |
| | | | |
| Window winder FR | \(\triangle \tr | | |
| Window winder RL | • | | |
| Window winder RR | | | |
| Rear view mirrors | ' | | |
| Radio (basic test only) | <i>'</i> | | |
| CD (basic test only) | ~ | | |
| Number of keys | 1 | | |
| Central locking | ~ | | |
| Remote locking | | ~ | |
| Sat. Nav. (basic test only) | | | ~ |
| Reversing camera | | | ~ |

Signature: