

Report ID: 26,496,509 Version: 1 13 Jan 2025 Created:

Make:	Lexus	Model:	IS250	Body Style:	Sedan		Pass	Fail	N/A	
Year:	2008	Registration:	HDD316	Reg Expiry:	12 Sep 2025	Engine				
WoF Expiry:	13 Jun 2025	Odometer:	94,180 Kms	Good No:	26496509	Oil level	~			
VIN:	JTHBK262505084650	Next Service:	106,000	Service Histor	y: No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty		for age and mileage	Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	charge.	Coolant condition	~			
	SC S	14/	CCW CCW			Performance	~			
Key:	ISC [S	<u>~</u> ∂	SC W SC W			Radiator / Hoses (visual)	· ·			
S = scratch						Transmission	Transmission			
D = dent	S SC			TIN		Operation	~			
R = rust PT = paint defe				r In		Noise	· ·			
C = crack] Clutch			~	
P = pin dent						CV joints	~			
* = decals	sc 916				ETP w	Wheel bearings	· ·			
SC = stone chips						Brakes				
W = significant scuffs SC S W SC SC SC						Performance				
		Notor con		may not be disr	laved in the diagram	Hand Brake	~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							-	ofture		
Good condition for age						Tyres (lowest observed tread depth of tyres) Left front 7 mm				
							_		mm	
						Right front	_	7	mm	
						Left rear		б	mm	
Conditions During Body Inspection: Dry									mm	
Under Carriage & Under Bonnet Inspection Comments						Spare Yes				
onder carriage & onder bonnet inspection comments						Suspension		1		
Good						Suspension performance			<u> </u>	
						Steering performance	~		ļ!	
						Shock absorbers	~			
						Air Conditioning / Heater	<u> </u>			
						Operation 🖌				
Interior Comments						Electrical / Accessories				
Seats	Average					Head lights	~			
Carpots	Deer					Tail lights	~			
Carpets	Poor					Indicators	~			
Panels	Good					Dashboard warning light	s 🖌			
						Wipers (front & rear)	~			
Dashboa	rd Good					Window winder FL	~			
						Window winder FR	~			
General C	<u>Comments</u>					Window winder RL	~			
Good						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)			~	
						Number of keys	1	I	4	
Road Conditions During Test Drive: Dry						Central locking	~			
						Remote locking	~		1	
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	~		1	
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	· ·		+	
									<u> </u>	
Inspected by: Tyler Le Bherz Date: 13 Jan 2025										

I have read and understood this condition guide.

Name:

Signature: