

Basic Vehicle Condition Guide

Report ID: 26,497,518


Version:

Created: 07 Jan 2025

Make: Model: Holden Captiva 5 **Body Style:** SUV Year: 2010 Registration: FGZ654 Reg Expiry: 23 Aug 2025 **Odometer:** WoF Expiry: 10 Mar 2025 226,302 Kms **Good No:** 26497518 VIN: KL3DD26FJAB036617 Next Service: 233400 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

Oil & Transmission Seepage - Expected for Age & Mileage Tyres Showing Age

| | Seats | Average |
|--|-----------|---------|
| | Carpets | Good |
| | Panels | Good |
| | Dashboard | Good |

Dry

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Beatrice Nelson Date: 06 Jan 2025

Name:

| | | 1 | | | |
|------------------------------|---------------|----------|----------|--|--|
| | Pass | Fail | N/A | | |
| Engine | | | | | |
| Oil level | ~ | | | | |
| Smoke & fumes | <i>y y</i> | | | | |
| Performance | ~ | | | | |
| Noise | ~ | | | | |
| Cooling System | | | 1 | | |
| Coolant condition | ~ | | | | |
| Performance | > > | | | | |
| Radiator / Hoses (visual) | ~ | | | | |
| Transmission | | | | | |
| Operation | / | | | | |
| Noise | > | | | | |
| Clutch | | | ~ | | |
| CV joints | ~ | | | | |
| Wheel bearings | ~ | | | | |
| Brakes | | | | | |
| Performance | ~ | | | | |
| Hand Brake | > | | | | |
| Tyres (lowest observed tread | depth | of tyre | es) | | |
| Left front | 2 | .5 | mm | | |
| Right front | 2.5 | | mm | | |
| Left rear | 2.0 | | mm | | |
| Right rear | ht rear 3 | | mm | | |
| Spare | | Yes | | | |
| Suspension | | | | | |
| Suspension performance | ~ | | | | |
| Steering performance | ~ | | | | |
| Shock absorbers | ~ | | | | |
| Air Conditioning / Heater | | | | | |
| Operation | ~ | | | | |
| Electrical / Accessories | | | 1 | | |
| Head lights | ~ | | | | |
| Tail lights | ~ | | | | |
| Indicators | ~ | | | | |
| Dashboard warning lights | ~ | | | | |
| Wipers (front & rear) | ンン | | | | |
| Window winder FL | ~ | | | | |
| Window winder FR | ~ | | | | |
| Window winder RL | ~ | | | | |
| Window winder RR | ~ | | | | |
| Rear view mirrors | ~ | | | | |
| Radio (basic test only) | ~ | | | | |
| CD (basic test only) | ' | | | | |
| Number of keys | 2 | <u> </u> | 1 | | |
| Central locking | ~ | | | | |
| Remote locking | ~ | | | | |
| Sat. Nav. (basic test only) | | | ~ | | |
| Reversing camera | | | ~ | | |
| <u> </u> | | | <u> </u> | | |

Signature: