

Report ID: 26,499,625 1 Version: 19 Dec 2024 Created:

Make:	Mitsubishi	Model:	Triton	Body Style:	Utility		Pass	Fail	N/A
Year:	2019	Registration:	MJP132	Reg Expiry:	29 May 2025	Engine	1		
WoF Expiry:	31 Dec 2025	Odometer:	189,619 Kms	Good No:	26499625	Oil level	~		
VIN:	MMAYLKL10LH000398	Next Service:	198,000	Service Histor	y: No	Smoke & fumes	~		
						Performance	r		
	port is not a warranty		for age and mileage	Parts have not	been dismontled or	Noise	r		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	SC	-0	S SC W	-161-		Radiator / Hoses (visual)	v		
S = scratch						Transmission			
D = dent	SC 6/6			TIN		Operation	~		
R = rust PT = paint def				í In	JHIH	Noise	~		
C = crack				+	SC	Clutch			~
P = pin dent	H				세비	CV joints	~		•
* = decals	sc 91			The	ETTP-	Wheel bearings	· ·		
SC = stone chips						Brakes			
W = significant scuffs P SC S P SC W						Performance			
		Note: son	ne defects & blemishes	may not be disn	laved in the diagram	Hand Brake	~		
Body Insp	pection Comments				ayea in the diagram		•	oftyre))
Aerial missing						Tyres (lowest observed tread depth of tyres) Left front 9 mm			
Aftermarket flat deck & toolbox fitted						Right front			mm
						Left rear			mm
						n			mm
Conditions During Body Inspection: Dry						Right rear 4 mm			mm
Under Carriage & Under Bonnet Inspection Comments					Spare Yes				
	indge a onder boi	meenspeede				Suspension			
4wd						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
						Electrical / Accessories			
Seats	Poor					Head lights	~		
Carpets	Average					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
	0000					Window winder FL	~		
Comoral						Window winder FR	~		
<u>General Comments</u>						Window winder RL			~
Drivers seat	t base torn					Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
	-		_			Remote locking	~		
-	ming Mechanism:	Timing				Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Andre Richardson Date: 19 Dec 2024									
Inspected by: Andre Richardson Date: 19 Dec 2024									

I have read and understood this condition guide.

Name:

Signature: