

Basic Vehicle Condition Guide

Report ID: 26,499,953


Version:

Created: 23 Dec 2024

Make: Model: Ssangyong **Actyon Sport Body Style:** Utility Year: 2014 Registration: HKL227 Reg Expiry: 21 Jul 2025 Good No: WoF Expiry: **Odometer:** 15 Nov 2025 126,102 Kms 26499953 VIN: Next Service: 127000 KPADA1ETSDP179373 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

No underbody inspection 4x4 untestedd

| Interior Comments | | | |
|-------------------|-----------------|--|--|
| Seats | holes, marks | | |
| Carpets | marks | | |
| Panels | wear, scratches | | |
| Dashboard | Good | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Melissa Wilson Date: 23 Dec 2024

| | Pass | Fail | N/A |
|------------------------------|--------------|---------|-----|
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | <i>V V</i> | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | | | |
| Coolant condition | ~ | | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | ! | |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | \(\times \) | | |
| CV joints | ~ | | |
| Wheel bearings | V | | |
| Brakes | | | 1 |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | d depth | of tyre | es) |
| Left front | 9 | .7 | mm |
| Right front | 10.5 | | mm |
| Left rear | 9 | | mm |
| Right rear | 9 | | mm |
| Spare | No | | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | ! | |
| Operation | ~ | | |
| Electrical / Accessories | • | | |
| Head lights | ~ | | |
| Tail lights | | | |
| Indicators | ~ | | |
| Dashboard warning lights | \(\times \) | | |
| Wipers (front & rear) | ~ | | |
| Window winder FL | \(\times \) | | |
| Window winder FR | ~ | | |
| Window winder RL | <i>v</i> | | |
| Window winder RR | ~ | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | ~ | | |
| Number of keys | 2 | | |
| Central locking | ~ | | |
| Remote locking | ~ | | |
| Sat. Nav. (basic test only) | | | ~ |
| Reversing camera | | | ~ |

I have read and understood this condition guide.

Name:

Signature: