

Basic Vehicle Condition Guide

Report ID: 26,500,608


Version:

Created: 19 Dec 2024

Make: Model: Volkswagen Golf **Body Style:** Wagon Year: 2014 Registration: HMA231 Reg Expiry: 06 Sep 2025 **Odometer:** WoF Expiry: **Good No:** 29 Aug 2025 83,754 Kms 26500608 WVWZZZAUZEP521315 **Next Service:** VIN: 93,640kms Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Front wheel drive.
Rear brake rotors rust.

| Interior | Comments |
|----------|----------|
| | |

| Seats | Average |
|-----------|---------|
| Carpets | Average |
| Panels | Good |
| Dashboard | Good |

General Comments

Roof rail lock key missing.

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No Kms:

Date: 19 Dec 2024

| | Pass | Fail | N/A | | |
|------------------------------|----------------------------|---------|-----|--|--|
| Engine | | | | | |
| Oil level | ~ | | | | |
| Smoke & fumes | v v | | | | |
| Performance | ~ | | | | |
| Noise | ~ | | | | |
| Cooling System | | • | | | |
| Coolant condition | ~ | | | | |
| Performance | ~ | | | | |
| Radiator / Hoses (visual) | ~ | | | | |
| Transmission | | | | | |
| Operation | ~ | | | | |
| Noise | ~ | | | | |
| Clutch | | | ~ | | |
| CV joints | ~ | | | | |
| Wheel bearings | ~ | | | | |
| Brakes | | • | | | |
| Performance | | ~ | | | |
| Hand Brake | ~ | | | | |
| Tyres (lowest observed tread | depth | of tyre | s) | | |
| Left front | 4 | 4 | mm | | |
| Right front | 3 | .8 | mm | | |
| Left rear | (| 5 | mm | | |
| Right rear | (| 5 | mm | | |
| Spare | | Yes | | | |
| Suspension | • | | | | |
| Suspension performance | ~ | | | | |
| Steering performance | ~ | | | | |
| Shock absorbers | ~ | | | | |
| Air Conditioning / Heater | | | | | |
| Operation | ~ | | | | |
| Electrical / Accessories | | | | | |
| Head lights | ~ | | | | |
| Tail lights | ~ | | | | |
| Indicators | ~ | | | | |
| Dashboard warning lights | ~ | | | | |
| Wipers (front & rear) | V V V V V V | | | | |
| Window winder FL | ~ | | | | |
| Window winder FR | ~ | | | | |
| Window winder RL | ~ | | | | |
| Window winder RR | ~ | | | | |
| Rear view mirrors | ~ | | | | |
| Radio (basic test only) | ~ | | | | |
| CD (basic test only) | ~ | | | | |
| Number of keys | 2 | | | | |
| Central locking | ~ | | | | |
| Remote locking | ~ | | | | |
| Sat. Nav. (basic test only) | | | ~ | | |
| Reversing camera | ~ | | | | |
| | | | | | |

I have read and understood this condition guide.

Takaya Murayama

Name:

Signature: