

Basic Vehicle Condition Guide

Report ID: 26,502,062


Version:

23 Dec 2024 Created:

Make: Model: Peugeot 308 **Body Style:** Hatchback Year: 2014 Registration: HQP239 Reg Expiry: 11 Feb 2025 **Odometer:** WoF Expiry: 21 Feb 2025 120,105 Kms **Good No:** 26502062 VIN: VF34C5FVADS104164 Next Service: 129000 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Minor stone chips on windscreen

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Front wheel drive

| <u>Interior Comments</u> | | | |
|--------------------------|------|--|--|
| Seats | Good | | |
| Carpets | Good | | |
| Panels | Good | | |
| Dashboard | Good | | |

General Comments

Battery light is on (battery or an electrical malfunction) turned off after 15 minutes but will still need to be investigated.

Rocket cover oil residue.

A/C does not go cold.

Remote battery needs replacing.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

23 Dec 2024 Jaykib Collins Inspected by:

| | Dana | Fa:I | NI/A |
|------------------------------|---------------------------------------|---------|----------|
| Position. | Pass | Fail | N/A |
| Engine | | | |
| Oil level | \(\times \) | | |
| Smoke & fumes | • | | |
| Performance | <i>V</i> | | |
| Noise | ~ | | |
| Cooling System | | 1 | |
| Coolant condition | V V | | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | | |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | depth | of tyre | es) |
| Left front | 3 | .5 | mm |
| Right front | 3.5 | | mm |
| Left rear | 5.0 | | mm |
| Right rear | 5.0 | | mm |
| Spare | Yes | | |
| Suspension | • | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | |
| Operation | | ~ | |
| Electrical / Accessories | | | |
| Head lights | ~ | | |
| Tail lights | V | | |
| Indicators | ~ | | |
| Dashboard warning lights | | ~ | |
| Wipers (front & rear) | ~ | | |
| Window winder FL | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | | |
| Window winder FR | ~ | | |
| Window winder RL | ~ | | |
| Window winder RR | ~ | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | ~ | | |
| Number of keys | 1 | | |
| Central locking | ~ | | |
| Remote locking | | ~ | |
| Sat. Nav. (basic test only) | | | _ |
| Reversing camera | ~ | | <u> </u> |